Work Orde	er ID 60060 8:29:40 AM		<u> </u>						-	- one depends	Page 1
Item ID: Revision ID: Item Name:	D4003-5 Fuel Pick Up Line	41	0	Accept				Setup	Start Stop		
Start Date: Required Date: Reference:		rt Qty: 200 q'd Qty: 2.09			Cust Item Customer:				Stop	4 (001) 46(0	
Approvals:	Process Plan: QC:	CL	Date: 10/6/2	_		ate:		Run	Start Stop		
Sequence ID/ Work Center II		ration cription		Set Up/	Tool ID	Tool # Pl					Insp.
Draw Nbr	Revision			Run Hours	}	C	ode Qty	Qty	<u> </u>	Number	Stamp
D4003	A										i
Doosan Lathe	<i>,</i>	Memo 1- Cut tube	as per dwg	0.00 0.00 0/06/2 9			E	K)		
QC Quality Control	QC2-	Inspect parts off m	nachine FAI/FAIB	0.00 0.00 10/06/2	7		3	b			
QC Quality Control	QC8-	Inspect parts - seco	and check	0.00 0.00	10/06/30		_3	, - ,B_			*

Dart Ae	rospac	e Ltd									
W/O:				W	ORK ORDER CHANG	ES			· · · · · · · · · · · · · · · · · · ·	•	
DATE	STEP		PRO	CEDURE CHANGE			у	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
		i									
Part No:			PAR #:	_ Fault Cate	egory:	_ NCR:	Yes(N	DQ	A : <u>/</u>	/ Date: _	10 A v E
	R	Resolutio	on:	_ Disposition	on:	_ QA: N	C Clo	sed:		Date: _	
NCR:			· W	ORK ORD	ER NON-CONFORMA	ANCE (I	NCR))		··	
DATE	STEP		Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	S	ign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspecto
	ios	ONE USE	PART FOR Welsing		10- 37 -09.	22	7				

NOTE: Date & initial all enties

Work Order ID 60060 June 24, 2010 8:29:40 AM											Page 2
Item ID: Revision ID:	D4003-5			Accept				Setup	Start		
Item Name:Fuel Pick Up LineStart Date:6/24/10Start Qty: 2.00Required Date:6/30/10Req'd Qty: 2.00Reference:					Cust Item ID: Customer:				Stop		
Approvals:	Approvals: Process Plan:QC:		Date:	- 8.	Date: Date:			Run	Start Stop		
Sequence ID/ Work Center II 150 HandFinish Hand Finishing	D	Operation Description Chemical Conversion Coa	at per QS1005 4.1	Set Up/ Run Hours 0.00	Tool ID Too	ol# Plan Code	Accept Qty	Reje Qty		eject	Insp. Stamp
QC Quality Control		QC3- Inspect Part Finish Memo	•.	0.00	10/02/08		<u> </u>	<u>-</u>	Ø	• <u> </u>	
170 Packaging Packaging		ldentify as per dwg & Stoo	ck Location: <u>I</u>	0.00	D/ 210.07.08	·	2	J	0	and the second seco	

. .

•

Dart Aerospace Ltd WORK ORDER CHANGES W/O: Approval **Approval STEP** DATE PROCEDURE CHANGE By Date Qtv Chief Eng / QC Inspector Prod Mar Part No: ______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: _____ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B Verification Description of NC **Approval** Approval DATE **STEP** Sign & **Action Description** Initial Section A Section C Chief Eng QC Inspector Date Chief Eng Chief Eng

NOTE: Date & initial all entries

Work Order ID 60060 June 24, 2010 8:29:40 AM										 	Page 3
Item ID: Revision ID: Item Name:	D4003-5 Fuel Pick Up	l ine		Accept					Setup	!	
Start Date: Required Date: Reference:	6/24/10	Start Qty: 2.00 Req'd Qty: 2.00			Cust It					Stop	
Approvals:	Process Plan:			Tooling:	Date:				Run	Start	
Sequence ID/		0	Date:	SPC (Y/N):		Date:				Stop	
Work Center II	D	Operation Description QC21- Final Inspection -	Work Order Release	Set Up/ Run Hours 0.00	Tool	D Tool#	Plan Code	Accept Qty	Rej Qty		Reject Insp. Number Stamp
QC Quality Control		Memo		0.00							mr /out
							H 4			1	10-7-8

1

. .

i

Dart Ae	rospace Lte	d						
W/O:			WO	RK ORDER CHANGES	3		· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PR	OCEDURE CHAN	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:	Date: _	
	Reso	lution:	Disposition	:	QA: N/C C	losed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCF	₹)		
		Description of NC	(Corrective Action Section		Verification	Approval Chief Eng	Approval QC Inspecto
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	& Section C		
						1		
							6	
,								
				**				
]	

NOTE: Date & initial all entries

Picklist Print

June 24, 2010 8:29:39 AM

Work Order ID: 60060

D4003-5

Parent Item Name: Fuel Pick Up Line



Start Date: 6/24/10

Start Qty: 2.00

Required Date: 6/30/10

Page 1

Required Qty: 2.00

Comments:

Parent Item:

IPP rev A 10.01.11 new issue Prelim EC verified by:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty	per Kit	Total Oty	Qty Issued	Date Issued	Status -
M6061T6T0.500W.035		Purchased	No			100	f	258.8900		3 11	6.315789			
6061-T6 RD Tube .500 x.035		(1811) BB168 IIE (1117 1 4 16 1							H				


6061-T6 RD Tube .500 x.035W

Location Loc Qty Loc Code MAT014 258.89 4692 258.89


9ft st 1006/28


Dart Aerospace Ltd WORK ORDER CHANGES W/O: **Approval Approval STEP** DATE PROCEDURE CHANGE By Qty Date Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: _____ Fault Category: ______ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B Description of NC Verification **Approval Approval STEP** DATE **Action Description** Sign & Initial Section C Chief Eng QC Inspector Section A Date Chief Eng Chief Eng


NOTE: Date & initial all entries





QTY. -049 2 ITEM NO. PART NUMBER JOHN CAMERON AVIATION PART NUMBER DESCRIPTION X D4003-049 TANK VENT LINE ASSEMBLY JCA-M47-2-17 2 D4003-9 VENT LINE 3 1 AN818-8D NUT MS20819-8D SLEEVE **D4003-049 TANK VENT LINE ASSEMBLY** 110 60060 NOTES:
1) MATERIAL: N/A
2) FINISH: N/A
2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D4003-049" AND B/N USING FINE POINT PERMANENT INK MARKER
7) WEIGHT: 0.11 lbs DESIGN DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. A D4003 MFG. APPR. SHEET 2 OF 9 APPROVED TITLE SCALE DE APPR LINE NTS DATE COPYRIGHT © 2010 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONTREHTML AND IS SUPPLED ON THE PRESS CONDITION TO BE USED FOR ANY PURPOSE OR COMPANY AND TO BE ARREST. 10.02.05 6

















DART AEROSPACE LTD	Work Order: 60068
Description: (-net pick up line	Part Number: 1 1005-5
Inspection Dwg: \$4003 Rev:	Page 1 of 1

	FIRS	T ARTICLE II	NSPECTION	ON CHE	CKLIST		
		X First Arti	cle	Prote	otype		
Drawing Dimension		Actual Dimension	Accept	Reject	Method of Inspection	Co	mments
35-01	= 030	36,00	35.				
2.88	=030	2876					
2.18	\$-030	2,276					
19	650-=	1.150					
-34	1.030	1.341					
-44	-,030	-44/					
0,098	7.005	0,100					
		·					
			·				
	,						
					~	1 -	

		1			· · · · · · · · · · · · · · · · · · ·		
	1						
Measured by:	17	Audited by:	and		Prototype Ap	proval:	N/A
Date:	10196/28	Date:	10/04/	30		Date:	N/A
Rev Date	Change	***************************************		-	Rev	ised by	Approved
Α	New Issue				KJ/.		1

H:\FORMS\Quality Assurance\approved QA\FAI revD